

4

3

2

1

F

F


1

E

E

D

D



- Open the box.

2

C


C

B

B

A

A



- Take out of the box.

4

3

2

1

4

3

2

1

F

F

3

Step-1

Step-1

Step-1

Step-1

E

E

D

D

4

Step-2

Step-2

C

C

B

B

A

A



4

3

2

1

20 Qty.
pop rivet
/ screw



4

3

2

1

F

F

5

2 Qty.




Step-3



E

E



Step-3


4 Qty
Screw

D

D

6

Step-4



Step-4



C

C

B

B

A

A

4

3



2

1

4 3 2 1

F

7




C

B


A


4 3 2 1

Type-1




Type-2







BOTTOM VIEW




DIMENSIONS IN
WIDTH AND HEIGHT




FRONT VIEW




SIDE VIEW



REAR VIEW




TOP VIEW




MAX/STD/MIN EQUIPMENT
MOUNTING DISTANCE

	H
4U	283
6U	372
7U	417
9U	506
12U	639
15U	772
16U	817



ISOMETRIC VIEW



EXPLODED VIEW